



ಕರ್ನಾಟಕ ಸರ್ಕಾರ

Office of the Assistant Executive Engineer, Public Works Department Division, Chintamani – 563 125	ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕಇಂಜಿನಿಯರ್‌ರವರಕಛೇರಿ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ಉಪ ವಿಭಾಗ, ಚಿಂತಾಮಣಿ – 563 125
ಇ-ಮೇಲ್: aecentkpwd@gmail.com Phone/Fax No: ದೂರವಾಣಿ/ಫ್ಯಾಕ್ಸ್ ಸಂಖ್ಯೆ: 08154-295058	

No. AEE/PWD/SD/AE/School Stability/2025-26/651

Dated ; 21/01/2026

BUILDING SAFETY CERTIFICATE


Annexure D

It is certified that the existing building or premises Shourya Academy School at Beside Shivakrishnavathi Layout, Oolavadi Road, Chintamani is having block(s)/ Floor(s) as per details below:

Detail of Block(s) in school	Block -1
No. of Floor(s) in the Block	G+3

The Building is owned/occupied by Shourya Academy have complied with the Building Safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of **Karnataka Public Works Department** on 06-01-2026 in the presence of The **Principle / Authorised Representative, Shourya Academy** and that the building/premises is fit for occupancy for running school for a period of ten years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The school should take necessary certificates from Fire department and other competent authorities within the time.
2. Building should be maintained neatly using good materials and experts.
3. The building should free from wall cracks, dampness, should take necessary action to fill cracks and avoid dampness in building, Patch plastering wherever necessary and periodically painting to be done.
4. The school should follow necessary safety precautions of students & teachers.
5. In the time of any changes in the structure of school building the school should take permission from competent authority. Otherwise this certificate will get cancelled without any conditions.
6. The school should maintain neatly of drinking water facility, toilet neatness and other conditions.


Assistant Executive Engineer,
P.W.D. Sub - Division,
Chintamani